



## BORE MEASURING STANDS

---

BMS-1



**1310**  
*Bore Measuring Stand*

**BMS-1**  
**1310**

### **Bore Measuring Stand**

For quick checks of bores in small work pieces. Hardened anvil plate can be raised with lever, thus moving test piece in to position. Anvil can be clamped at any height for checking eccentricity.

CODE NO.	CLAMPING STEM DIAMETER	MAXI WORKING HEIGHT	FINE ADJUSTING RANGE	MASS Kg	REMARKS
1310	15mm	—	—	6	

